



Invoice

4/29/2024

2584 Horse Pasture Rd
 Virginia Beach, VA 23453
 Office 757-340-9882
 Fax 757-340-9836

BILL TO Tides at Newmarket Creek Condo Association
10 Rosiland Way
Hampton, VA 23669
757-214-3668
757-345-3817
sdyoung@unitedpropertyassociates.com

Description	Amount
Fiberglass Repair - Cut out cracked area around step in deep end of pool. Build backing block and glue in sister catches. Glue cut out pieces back in. Once cured grind out around repaired area 6-8 inches beyond repair. Glass with multiple layers of 1708 fiberglass. Once cured grind and feather edges. Apply faring filler. Sand and fare. Fill lows and imperfections sand and fare. Prime with matching gel coat. Sand and fare. Sand around repaired area with 600 grit. Clean/ tape/ plastic. Wipe down and spray multiple layers of matching gel coat. Once cured wet sand in progression from 180- 1500. Compound. Remove tape and plastic. Fill dings on steps. Fare. Prime. Sand fare. Spray with matching gel coat. Wet sand and compound. - price includes all labor/ materials/ travel cost to do repair to completion ** estimate for one corner/ corner that is cracked. If deemed other side needs to be repaired than double estimate.	\$7,950.00
TOTAL BALANCE	\$7,950.00

Payments as follows;
1st payment at contract signing \$7,000
2nd payment at completion \$950
No other terms or conditions of the above mentioned contract shall be negated or changed as a result of this here stated.
Start work within 60 days. Pending weather.

THANK YOU FOR YOUR BUSINESS!